Botao Sun <botao.sun@linaro.org>

Test Result Summary of Calendar Week 16, 2013 for Linux Linaro ubuntu Quantal.

Botao Sun <botao.sun@linaro.org>   Thu, Apr 18, 2013 at 1:09 PM
To: linaro-release <linaro-release@lists.linaro.org>
Cc: linaro-dev <linaro-dev@lists.linaro.org>

Calendar Week 16, 2013: Here is test result summary for Linux Linaro ubuntu Quantal image on following boards:

1) ARM Versatile Express A9;
2) Samsung Arndale;
3) TI Panda 4430;
4) TI Panda 4460;
5) ST Ericsson Snowball.

Synopsis: Gator version mismatch issue has been solved except on TI Panda image, the status of all other features remains the same as previous week.

1. ARM Versatile Express A9 + Linux Linaro Quantal (Column R):

https://docs.google.com/a/linaro.org/spreadsheet/ccc?key=0AroPySpr4FnEdFNmV3gyZWRGVS12Y
UhqeW9rdkVZdmc#gid=1

DS-5 data streaming backs to work with new gator version on target, "Halt" and "Device Tree" are unavailable, all other features work well.

2. Samsung Arndale + Linux Linaro Quantal (Column L):

https://docs.google.com/a/linaro.org/spreadsheet/ccc?key=0AgB-fT5LL31CdGZJSFdTUWFFYVdhZl8wMF
pxLXd2TXc#gid=0

Kernel panic is occurred during power management test, all other features work well.

3. TI Panda 4430 + Linux Linaro Quantal (Column R):

https://docs.google.com/a/linaro.org/spreadsheet/ccc?key=0AroPySpr4FnEdEwwZkhrZ1VYUEg2L
TlQZzR0RlhzM3c#gid=3

Status is remained as same as last week: WiFi and display output are unavailable, several test cases failed in power management, DS-5 failed due to gator version mismatch, all other features work well.

4. TI Panda 4460 + Linux Linaro Quantal (Column R):

https://docs.google.com/a/linaro.org/spreadsheet/ccc?key=0AroPySpr4FnEdEwwZkhrZ1VYUEg2L
TlQZzR0RlhzM3c#gid=4

Kernel panic happens during power management test, WiFi & Display are unavailable. DS-5 test failed due to gator version mismatch, all other features work well.

5. ST Ericsson Snowball + Linux Linaro Quantal (Column S):

https://docs.google.com/a/linaro.org/spreadsheet/ccc?key=0AroPySpr4FnEdFJ4X0NjWjJteVlXL
VJFSHFuOHo1c2c#gid=1

HDMI display and Reboot are unavailable; "thermal_03.1" test failed in power management; some I/O errors got observed in SD MMC test, all other features work well.