Botao Sun <botao.sun@linaro.org>

Linaro ubuntu Test Result Summary for 12.10 release (Calendar Week 43).

Botao Sun <botao.sun@linaro.org>
To: linaro-release <linaro-release@lists.linaro.org>
Cc: linaro-dev <linaro-dev@lists.linaro.org>
Thu, Oct 25, 2012 at 7:48 PM

Linaro 12.10 Release (Calendar Week 43): Here is test result summary for Linaro ubuntu image on following boards:

1) ARM Versatile Express A9;
2) Samsung Origen;
3) TI Panda Board 4430;
4) TI Panda Board 4460.

Synopsis: No change on feature status for vexpress A9 and Samsung Origen. Audio over HDMI and 3.5mm Jack Ports works well on another Panda 4430 board which is currently held by another colleague. Suspend / Resume works well on Panda 4460 but still failed on 4430.

1. vexpress A9 + ubuntu (Column AF):

https://docs.google.com/a/linaro.org/spreadsheet/ccc?key=0AroPySpr4FnEdFNmV3gyZWRGVS12Y UhqeW9rdkVZdmc#gid=0

Features' status is exactly same as previous week. Device Tree is still unavailable and ARM landing team will continue their work on this. Video playback is unavailable either.

2. Origen + ubuntu (Column AA):

https://docs.google.com/a/linaro.org/spreadsheet/ccc?key=0AroPySpr4FnEdEowNWhZRi1zbDNNV Uw1amhXTUdPcVE#gid=0

Now Power Management test doesn't hang the board, but still have many failed test result. WiFi, Bluetooth, Unity 3D, HDMI and Video Playback are still unavailable.

3. Panda 4430 + ubuntu (Column AC):

https://docs.google.com/a/linaro.org/spreadsheet/ccc?key=0AroPySpr4FnEdEwwZkhrZ1VYUEg2L TlQZzR0RlhzM3c#gid=0

Audio over HDMI and 3.5mm Jack Ports works well on another Panda 4430 board, and this will lead us to consider more about the hardware issue. The other features remain the same.

4. Panda 4460 + ubuntu (Column AB):

https://docs.google.com/a/linaro.org/spreadsheet/ccc?key=0AroPySpr4FnEdEwwZkhrZ1VYUEg2L TlQZzR0RlhzM3c#gid=1

Suspend / Resume now works well on this build, but the Power Management test popped up an old failure again. All other features remain the same, dead lock error is still in the boot log and Audio input over 3.5mm Jack Port is unavailable.

For the previous week (Calendar week 42) summary, please refer to attachment.

Thank you.

Best Regards
Botao Sun