

---

## Test Result Summary of Calendar Week 41 for Linaro ubuntu.

---

**Botao Sun** <botao.sun@linaro.org>  
To: linaro-release <linaro-release@lists.linaro.org>  
Cc: linaro-dev <linaro-dev@lists.linaro.org>

Fri, Oct 12, 2012 at 10:20 PM

Calendar Week 41: Here is test result summary for Linaro ubuntu image on following boards:

- 1) ARM Versatile Express A9;
- 2) Samsung Origen;
- 3) TI Panda Board 4430;
- 4) TI Panda Board 4460.

Synopsis: No change on feature status for vexpress A9 & Samsung Origen boards. Both HDMI & DVI-D back to work on Panda 4430 & 4460. For SD card flashing, now command "dd" backs to work on all images.

1. vexpress A9 + ubuntu (Column AD):

<https://docs.google.com/a/linaro.org/spreadsheet/ccc?key=0AroPySpr4FnEdFNmV3gyZWRGVS12YUhqeW9rdkVZdmc#gid=0>

Features' status is exactly same as previous week.

2. Origen + ubuntu (Column Y):

<https://docs.google.com/a/linaro.org/spreadsheet/ccc?key=0AroPySpr4FnEdEowNWhZRi1zbDNNVUw1amhXTUdPcVE#gid=0>

Features' status is exactly same as previous week.

3. Panda 4430 + ubuntu (Column AA):

<https://docs.google.com/a/linaro.org/spreadsheet/ccc?key=0AroPySpr4FnEdEwwZkhrZ1VYUEg2LTIQZzR0RlhzM3c#gid=0>

Audio over HDMI doesn't work, and this causes no sound can be heard when using "rhythmbox" to play music. Bluetooth now let system crashes again, after pairing process. Also, system crashes during the Power Management test "lava-test run pwrmgmt", with log output flushing in serial console.

4. Panda 4460 + ubuntu (Column Y):

<https://docs.google.com/a/linaro.org/spreadsheet/ccc?key=0AroPySpr4FnEdEwwZkhrZ1VYUEg2LTIQZzR0RlhzM3c#gid=1>

The test result on Panda 4460 is quite different with Panda 4430. On TI Panda 4460 board, Audio over HDMI works well, Bluetooth headset works well, and Power Management test works well. Even suspend / resume starts to work, although many error log output flushes in serial console.

For the previous week (Calendar week 40) summary, please refer to attachment.

Thank you.

Best Regards  
Botao Sun

